


N18MD
LogBook #3
LEFT



PROPPELLER LOGBOOK

Beech D55

Owner Name _____

Address _____

low: 13.0

High: 18.5

feather: 83.0

Propeller Model

PHC-C3YF-2VF

Blade Model

FC7663-2R

Hub Serial No.

EB3411A

Blade Serial No. 1

H53224

2

H53220

3


H53231

4

INSTALLATION HISTORY

Date	Aircraft Model & Registration Number	Engine Serial Number & Position
May 12, 2022	Boeing IDS S/O TE-455 N18MD	CH IO-550C S/O 684240
	WAS	
	2150161 301V15C	
	dlhw bdlqmoa s'j'2 .s'8'2 .s'0.A 11A	
	slnt 10 sltstb insntt39 .stsb 01	
	OWstbnu ell pss s'c l'uchavo	
	:y'lttstb n'eqs1 p'ltwollol s'lt 1c	
0388588		
	.onl .j'ns r'ellagol'9 nosnhol	
	NOT 191.12 nol'siVA 11S	
	0852E AD 101612	
	084S-002-130	
	L104196L 52110 AAF	

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures Repairman and Station Certificate Numbers
Jan 3 2022		11011	Propeller completely overhauled DAW. OHA 1170 rev. 19, Bohn 1336 New 40, SPM 2024 Service Manuals	
			All A.D.'s, S/B's, S/L's complied with to date. Pertinent details of this overhaul are on file under W.O. 021-502 at the following repair facility:	
				Juan Salais 3826866
			Johnson Propeller Ent., Inc. 211 Aviation St. hgr 104 Shafter, CA 93263 661-399-2480 FAA-CRS# J3PR491J	

Note: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

MAINTENANCE & SERVICE HISTORY

[illegible]

Note: Enter Compliance With All Applicable FDA A.D. & Factory Service Bulletins On Pages 11 & 12



GOLD SEAL AIRCRAFT ENGINES

21 Creative Pl. Montrose, CO 81401
(970) 249-0232 800-575-9929
Fax: (970) 249-4135
www.westernskyways.com

Date: 6 April 2023

Tach time: 156.9

Total time:

Aircraft Model: Beech D55

#1 Engine Model: Cont IO-550-C

#2 Engine Model:

#1 Prop Model: Hart PHC-C3YF-2UF/FC7663B-2R

#2 Prop Model:

Reg. Number: N18MD

Hobbs Time: 2196.8

Work Order Number: B001280

Serial Number: TE-455

Total time: 1879.9

Total time:

Total time: Unknown

Total time:

TSO: 167.5

TSO:

TSO: 0

TSO:

Removed propeller PHC-C3YF-2UF/FC7663B-2R for repairs.

Installed overhauled propeller PHC-C3YF-2UF/FC7663B-2R serial number EB8411A. Installed 2 new nut plates on spinner bulkhead.

Ground run, leak and operational checks good.

Ryan Dickerson

Airframe and Powerplant 2670501

Twin Oaks Aircraft Maintenance, LLC

Daniel W Stark

12405 SW River Road

Hillsboro, OR. 97123

danny@twinoksaircraft.com

Tach: 2215.1 & LPTSMOH: 188.8

8/17/2023

Beech D55

Continental IO-550-C7F

Hartzell PHC-C3YF-2UF

N18MD

S/N: TE-455

S/N LH: 684240

RH: 271786-R

S/N LH: EB3411A

RH: EB3410A

Completed annual inspection per service manual and FAR 43 appendix D. I certify this propeller was inspected IAW an annual inspection and was determined to be in airworthy condition.

Daniel W Stark 2708377 1A

Note: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

(541) 482-7675

**natures
Station
bers**

A&P 3737996 1A

[illegible]

—