

☐ **HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS**

WO: 5259

Propeller L - page 1 of 1



Waypoint Aviation Services · 6873 Flight Rd. · Riverside, CA 92504 · 888-624-6826

Year: -
Date: -
Next In
Due: -

N18MD

Hobbs: 1841.3

Hartzell, PHC-C3YF-2UF, S/N: EB3411A

PTSO: 2057.3

April 1, 2020

Year: -

Date: -

Next In
Due: -

I certify this propeller was repaired and inspected in accordance with an annual inspection and was found to be in an airworthy condition. Serviced propeller hub with nitrogen.

All airworthiness directives through January 2020 checked for compliance and recurrence.

This propeller identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Details of the work performed are on file with Waypoint Aviation Services under work order 5259.

Year: -

Date: -

Matthew LaPrade A&P IA 3741762

Next Inspection
Due: -

Time Since
Overhaul

Mech. Cert. # or Repair Station #

Twin Oaks Aircraft Maintenance, LLC

Daniel W Stark
 12405 SW River Road
 Hillsboro, OR 97123
 danny@twinoksaircraft.com
 Tach: 1930.5 & LPTSMOH: 2146.5

5/19/2021
 Beech D55
 Continental IO-550-C7F

N18MD

Hartzell PHC-C3YF-2UF

S/N: TE-455
 S/N LH: 271787-R
 RH: 271786-R
 S/N LH: EB3411A
 RH: EB3410A

Completed annual inspection per service manual and FAR 43 appendix D. I certify this propeller was inspected LAW an annual inspection and was determined to be in airworthy condition.

Daniel W Stark 2708377 1A

NS ☐

Year: _____	Total Time in Service	Description	
Date: _____			
Next Inspection Due: _____	Time Since Overhaul		
		Mech. Cert. # or Repair Station # _____	
Year: _____	Total Time in Service	Description	
Date: _____			
Next Inspection Due: _____	Time Since Overhaul		
		Mech. Cert. # or Repair Station # _____	